

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: South	DESCRIPTION	View from road on north part of site to south. General photo of tanks.	1 (482)
	CLIENT	U.S. EPA	Date 4/7/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	View from road on east-central portion of site to west.	2 (483)
	CLIENT	U.S. EPA	Date 4/7/14
	PHOTOGRAPHER	L. Rectenwald	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	View of tank from west to east on east-central portion of site.	3 (484)
	CLIENT	U.S. EPA	Date 4/7/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	View of SB15 0-5' core on table with clean plastic, PID, zipper bags, knife, logbook	4 (485)
	CLIENT	U.S. EPA	Date 4/8/14
	PHOTOGRAPHER	L. Rectenwald	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	View of SB15 location with Geoprobe rig and crew.	5 (486)
	CLIENT	U.S. EPA	Date 4/8/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	View of SB15 intervals 0-5, 5-10,10-15 with labeled VOC screening bags.	6 (487)
	CLIENT	U.S. EPA	Date 4/8/14
	PHOTOGRAPHER	L. Rectenwald	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	View of SB15 composites in jars with labels taped on tags, log	7 (488)
	CLIENT	U.S. EPA	Date 4/8/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	View of SB16 core location with table in foreground top of core at far left.	8 (489)
	CLIENT	U.S. EPA	Date 4/8/14
	PHOTOGRAPHER	L. Rectenwald	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	View of SB17 core location from South facing North. Samples bagged for VOC screen on table.	9 (490)
	CLIENT	U.S. EPA	Date 4/8/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	View of SB17 core location and table, composites prepared to go in jars.	10 (491)
	CLIENT	U.S. EPA	Date 4/8/14
	PHOTOGRAPHER	L. Rectenwald	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	View of SB12 0-5' on tabletop at far left.	11 (492)
	CLIENT	U.S. EPA	Date 4/9/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	View of SB12 0-5' and 5-10' cores. Coolers in background.	12 (493)
	CLIENT	U.S. EPA	Date 4/9/14
	PHOTOGRAPHER	L. Rectenwald	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: NW	DESCRIPTION	View from SB14 to NW across pond toward site structures.	13 (494)
	CLIENT	U.S. EPA	Date 4/9/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: South	DESCRIPTION	View of SB14 cores 0-20 feet, top at far left, bottom at near right, rig in back.	14 (495)
	CLIENT	U.S. EPA	Date 4/9/14
	PHOTOGRAPHER	L. Rectenwald	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	View of work table and supplies. Plastic underneath to protect against spills.	15 (496)
	CLIENT	U.S. EPA	Date 4/9/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: South	DESCRIPTION	View of rig and crew preparing to install well at SB14.	16 (497)
	CLIENT	U.S. EPA	Date 4/9/14
	PHOTOGRAPHER	L. Rectenwald	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: South	DESCRIPTION	View of crew placing filter sand at SB14.	17 (498)
	CLIENT	U.S. EPA	Date 4/9/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	View of crew installing well at location SB9.	18 (499)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	View of crew installing well at location SB9.	19 (500)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	



**Gregg County Refinery**

REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	View of crew installing well at location SB9.	20 (501)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	



# Sampling and Analysis Support Longview, Texas



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	View of SW corner of property north of SB11 showing nearly inundated road bed.	21 (502)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: SE	DESCRIPTION	View NW to SE at location SB13	22 (2008)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	SB10 core 0-5 and 5-10 ft interval. Top on far left always.	23 (2009)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	SB10 cores 10-15 feet and 15-20 feet.	24 (2010)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: South	DESCRIPTION	SB10 drill location. View is to the south.	25 (2012)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	Standing water east of SB10.	26 (2014)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: SW	DESCRIPTION	Drillers at location SB10. The view is looking from the NE to SW.	27 (2017)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction:SW	DESCRIPTION	Drillers at location SB10 view from NE to SW	28 (2018)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	View of bags of filter sand and hole plug (bentonite) used at SB10 from E to W	29 (2019)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	Drillers at location SB10. Good view of road. A flush mounted well.	30 (2020)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	Drillers at location SB10, tank in background.	31 (2021)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	




REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	Drilling rig proximity to tanks at Gregg Refining.	32 (2022)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: NE	DESCRIPTION	View of tables from SW facing NE. Core SB10 on table. VOC screen in bags.	33 (2025)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	




REPA Zone 2 Project 6609 Direction: NE	DESCRIPTION	SB9 core view from SW facing NE.	34 (2026)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: NE	DESCRIPTION	View of tables from SW facing NE. Core SB10 on table. VOC screen in bags.	35 (2025)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: NE	DESCRIPTION	SB9 core view from SW facing NE. Top always on far left.	36 (2026)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: South	DESCRIPTION	SB11 core 10-15 and 15-20 feet intervals and saddle tank. View from north facing south.	37 (2027)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	SB11 core 0-5 and 5-10 feet intervals. View from east facing west.	38 (2028)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	SB21 location (former SB17 and current MW17) 0-5' core top far left.	33 (2040)
	CLIENT	U.S. EPA	Date 4/14/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	MW17 with SB21 flag in rear	34 (2041)
	CLIENT	U.S. EPA	Date 4/14/14
	PHOTOGRAPHER	L. Rectenwald	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	SB20 core 0-5', 5-10'	35 (2043)
	CLIENT	U.S. EPA	Date 4/14/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	SB20 adjacent to MW16	36 (2044)
	CLIENT	U.S. EPA	Date 4/10/14
	PHOTOGRAPHER	L. Rectenwald	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	SB20 table cores 10-15' and 15-20'	37 (2045)
	CLIENT	U.S. EPA	Date 4/14/14
	PHOTOGRAPHER	L. Rectenwald	



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	SB19 table under shed. Core location adjacent to MW15.	38 (2046)
	CLIENT	U.S. EPA	Date 4/14/14
	PHOTOGRAPHER	L. Rectenwald	




**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	SB19 table under shed due to thunderstorm.	39 (2047)
	CLIENT	U.S. EPA	Date 4/14/14
	PHOTOGRAPHER	L. Rectenwald	

New Photo Log starts below  
(new page)


**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Soil bore 15 drum label. 4-8-14	01 (IDW1-SO)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Drum containing soil bore 15. 4-8-14 label.	02 (IDW2-SO)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Label on drum containing soil bore 16. 4-8-14	03 (IDW3-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	




REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	Label on drum containing soil bore 17. 4-8-14	04 (IDW4-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Label on drum containing soil bores 14-18 and 12. 4-8-14	05 (IDW5-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Label on drum containing soil bore 18. 4-8-14	06 (IDW6-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Label on drum containing soil bore 16, 18 and 12. 4-8-14	07 (IDW7-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Label on drum containing soil. 4-8-14	08 (IDW8-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Label on drum containing soil bore 14. 4-8-14	09 (IDW9-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Label on drum containing soil bore 9. 4-10-14	10 (IDW10-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Label on drum containing soil bore 11 and 14. 4-10-14	11 (IDW11-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Label on drum containing soil bore 10. 4-10-14	12 (IDW12-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Label on drum containing soil bore 13. 4-10-14	13 (IDW13-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Label on drum containing soil bore 11 and 13. 4-10-14	14 (IDW14-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Label on drum containing PPE Core Plastic. 4-10-14	15 (IDW15-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Label on drum containing PPE. 4-10-14	16 (IDW16-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Label on drum containing soil bores 9, 10 and 13. 4-10-14	17 (IDW17-S0)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Decontamination water 4-8-14 label on drum.	01 (IDW1-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Decontamination water label. 4-18-14	02 (IDW2-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Decontamination water label. 4-9-14 on drum.	03 (IDW3-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Decontamination water label. 4-9-14 on drum.	04 (IDW4-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Decontamination water label. 4-10-14 on drum.	05 (IDW5-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Purge water MW2. 4-17-14 label on drum.	06 (IDW6-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Decontamination water label. 4-10-14 on drum.	07 (IDW7-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Purge water label. 4-10-14 on drum.	08 (IDW8-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Decontamination water label. 4-10-14 on drum.	09 (IDW9-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	MW2 label on drum. 4-11-14	10 (IDW10-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Purge from MW3, 4, 5, 6. 4-11-14 label on drum.	11 (IDW11-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Purge from MW10. 4-11-14 label on drum.	12 (IDW12-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Purge water MW1 and 18. Label 4-11-14 on drum.	14 (IDW14-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**




REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Purge water MW 18, 17, 16 and 11. Label on drum 4-12-14.	15 (IDW15-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	



REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Decontamination water. MW9 4-12-14 label on drum.	16 (IDW16-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	

**Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: N/A	DESCRIPTION	Decontamination water MW1, 11 and 12. Label and drum 4-10-14.	17 (IDW17-WA)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	L. Arthur	



REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	Monitoring well one. East side of property.	01 (MW1)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	Monitoring well three. West side of property.	03 (MW2)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	Monitoring well four. West side of property.	04 (MW4)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



**Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	Monitoring well five. West side of property.	05 (MW5)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	Monitoring well six. West side of property.	06 (MW6)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	Monitoring well seven. West side of property.	07 (MW7)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: South	DESCRIPTION	Monitoring well eight. South side of property.	08 (MW8)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: NWest	DESCRIPTION	Monitoring well nine. Northwest side of property.	09 (MW9)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: SWest	DESCRIPTION	Monitoring well eleven. Southwest side of property.	11 (MW11)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	Monitoring well twelve. South side of property.	12 (MW12)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: SEast	DESCRIPTION	Monitoring well thirteen. Southeast side of property.	13 (MW13)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	

# **Sampling and Analysis Support Longview, Texas**



REPA Zone 2 Project 6609 Direction: SEast	DESCRIPTION	Monitoring well fourteen. East side of property.	14 (MW14)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	Monitoring well fifteen. East side of property.	15 (MW15)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	Monitoring well sixteen. East side of property.	16 (MW16)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	Monitoring well seventeen. Central property.	17 (MW17)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	Monitoring well eighteen. Central property.	18 (MW18)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: SE & N	DESCRIPTION	Soil sample one. Southern property boundary.	01 (SS1)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: SE & N	DESCRIPTION	Soil sample one. Southern property boundary. PICTURE 2	01-2 (SS1-2)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: SEast	DESCRIPTION	Soil sample two. Southwest side of property.	02 (SS2)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	Soil sample three. North side of property.	03 (SS3)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	Soil sample four. North side of property.	04 (SS4)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	Soil sample four. North side of property. PICTURE 2	04-2 (SS4-2)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	Soil sample five. North side of property.	05 (SS5)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	Soil sample five. North side of property. PICTURE 2	05-2 (SS5-2)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: SEast	DESCRIPTION	Soil sample five. North central property. PICTURE 3	05-3 (SS5-3)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	Soil sample six. North central property.	06 (SS6)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: S & N	DESCRIPTION	Soil sample eight. North side of property.	08 (SS8)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: North	DESCRIPTION	Soil sample eight. North side of property. PICTURE 2	08-2 (SS8-2)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: SW	DESCRIPTION	Soil sample nine. North side of property.	09 (SS9)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	Soil sample ten. North side of property.	10 (SS10)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	Soil sample ten. North side of property. PICTURE 2	10-2 (SS10-2)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction:	DESCRIPTION	Soil sample eleven.	11 (SS11)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: East	DESCRIPTION	Soil sample twelve. West side of property.	12 (SS12)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: NWest	DESCRIPTION	Soil sample thirteen. North side of property.	13 (SS13)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: S & N	DESCRIPTION	Soil sample thirteen. North side of property.	013-2 (SS13-2)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: NEast	DESCRIPTION	Soil sample fourteen. Southwest side of property.	14 (SS14)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: NEast	DESCRIPTION	Soil sample fifteen. North side of property.	015 (SS15)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: NEast	DESCRIPTION	Soil sample sixteen. West side of property.	16 (SS16)
	CLIENT	U.S. EPA	Date 4/18/14
	PHOTOGRAPHER	K. Heffentrager	



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	MW-11 looking west	01 (1)
	CLIENT	U.S. EPA	Date 4/17/14
	PHOTOGRAPHER	J. Van Dyke	



**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	MW-11 looking west	02 (2)
	CLIENT	U.S. EPA	Date 4/17/14
	PHOTOGRAPHER	J. Van Dyke	



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	MW-11 looking west	03 (3)
	CLIENT	U.S. EPA	Date 4/17/14
	PHOTOGRAPHER	J. Van Dyke	

**Gregg County Refinery  
Sampling and Analysis Support  
Longview, Texas**



REPA Zone 2 Project 6609 Direction: West	DESCRIPTION	MW-11 looking west	04 (4)
	CLIENT	U.S. EPA	Date 4/17/14
	PHOTOGRAPHER	J. Van Dyke	

**End of Log**